<u>*=</u>	NIAGARA CATHOLIC DISTRICT SCHOOL BOAR SCHOOL BOARD VENTILATION PROFILE	
	Select your school here	
School Name	Notre Dame College School (Welland)	222222222
Ventilation System	Mechanical Ventilation	
	11 1	
School Ventilation and F	iltration Measures*	4
		4
Ventilation assessed		4
Ventilation assessed Running ventilation systems l	onger	4
Ventilation assessed Running ventilation systems lo Higher grade filters installed Increased frequency of filter cha	onger	4
Ventilation assessed Running ventilation systems look Higher grade filters installed Increased frequency of filter cha	onger	4 4 4

^{*}Some measures may not be feasible within the context of a school facility/site and related building systems.

^{**}High-Efficiency Particulate Air (HEPA)